

## **SB 88-110 – Notice of wire filter replacement**

2018-11-16  
Rev. A

### **1 Scope and Target Group**

#### **⚠ WARNING**

- ✓ Always refer to the user manual for additional information and safety warnings.
- ✓ Only perform this task if you are qualified to carry out the steps described below.
- ✓ Always make sure that the tasks described in this bulletin are intended for the equipment you are working on.
- ✓ If you are unsure about the workflow, steps or qualification, contact your TTS aftersales service contact.

#### **Your aftersales service contact:**

TTS Marine GmbH  
An der Reeperbahn 6  
D-28217 Bremen  
Germany  
Telephone: +49(421) 520 08-0  
Telefax : +49(421) 52008-749  
E-Mail: [service@ttsgroup.com](mailto:service@ttsgroup.com)



## 2 Introduction and background

This Service Bulletin gives you an overview of the reason for the switch from a wire filter to a paper filter in the pump station as well as a detailed list of article numbers (old and new).

During the development of the new control block (NG25 and NG32), it was decided that the wire filter in the pump station should be replaced with a paper filter to meet the increasing demands of oil quality.

<b>NOTICE</b>	Please note that this change is only for the CSH winches.
<b>NOTICE</b>	The replacement of the filter is 1:1

FOR CUSTOMER USE ONLY



### 3 Overview of article numbers

This is an overview of the new filter article numbers. This also explains which filter element belongs to which filter.

Item	Old article number	New article number	Corresponding filter element	Article number
Filter	4004005	5301662	spare – filter element	5301666
Filter	4003910	5301661	spare – filter element	5301665
Filter	4003186	5301663	spare – filter element	5301667